



3 611 C35 100
 Issue
 Stand } 14-11-11








Fig./Abb. 1



Modifications reserved
 Änderungen vorbehalten
 Modifications réservées
 Salvo modificaciones



★ mit Loctite 222 sichern
 secure with Loctite 222



● = Pos. 896 1 617 000 497 Service Pack ohne Fett
 1 617 000 497 Service pack without grease
 ● = Pos. 895 1 617 000 702 Service Pack mit Fett
 1 617 000 702 Service pack with grease